

Oil Field Environmental Incident Summary

Incident: TMC00000004

Date/Time of Notice: 01/28/2013 11:44

Responsible Party:

Well Operator: HESS CORPORATION

Well Name: EN HORST 54-92 BAKKEN FACILITY

Field Name: ROBINSON LAKE

Well File #:

Date Incident: 8/26/2012

Time Incident: 00:00

Facility ID Number: 216981-01

County: MOUNTRAIL

Twp: 154

Rng: 93

Sec: 3

Qtr: LO T1

Location Description:

Submitted By: Brian Epperson

Received By:

Contact Person:

3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

2 Miles

Distance Nearest Water Well:

2 Miles

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels	0	barrels
Brine	1.79	barrels	0	barrels	0	barrels
Other	0	barrels	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/18/2013

Clean Up Concluded: 8/26/2012

Risk Evaluation:

environmental

Areal Extent:

Potential Environmental Impacts:

Soil impacted by salt water soaking into the ground on site.

Action Taken or Planned:

EarthMovers will clean up the area and the affected material will be taken to Clean Harbors

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 1/29/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, according to the report.